



## SUMO 350

### Sumo

Weatherproof, IP65, Vandal resistant optional emergency light

- Die cast aluminium, powder coated finish, opal polycarbonate lens
- Stainless steel allen head trim screws
- Weatherproof IP65
- Vandal resistant
- Manufactured to comply with ASNZS 60598 and ASNZS CISPR 15:2006
- Various emergency versions available

### Specifications

#### ■ How to specify colour

White **W**

Black **B**

Silver **S**

(Order example: NSM218E/■

becomes NSM218E/W ie. white body)

### SUMO 350



Sumo 350	Open Face	Grill Face	Screen Face
1 x 26W G24d3	NSM126/■	NSG126/■	NSS126/■
2 x 18W G24d2	NSM218/■	NSG218/■	N/A
2 x 18W G24q2 HF NON DIM	NSM218E/■	NSG218E/■	N/A
2 x 18W G24q2 DALI DIMM	NSM218DALI/■	NSG218DALI/■	N/A
2 x 26W G24d3	NSM226/■	NSG226/■	N/A

### SUMO 350 Emergency



Sumo 350 Emergency	Open Face	Grill Face	Screen Face
Maintained Emergency – 2 x 18W G24q2	NSM218CE/■	NSG218CE/■	N/A
Maintained Emergency – 1 x 26W G24q3	NSM126CE/■	NSG126CE/■	N/A
Stanilite Nexus Monitored Maintained Emergency – 1 x 26W G24q3	NSM126ME-NS/■	NSG126ME-NS/■	N/A
Clevertronics Zone Works Monitored Maintained Emergency 2 x 18W G24q2	NSM218ME-ZCP/■	NSG218ME-ZCP/■	N/A
Tridonic DALI Monitored Maintained Emergency 2 x 18W G24q2	NSM218DALI-ME/■	NSG218DALI-ME/■	N/A



## Emergency Classifications

### Maintained Emergency – 2x18w

Part Code Open Face: NSM218CE

Part Code Grill Face: NSG218CE

**Classifications:**

Ceiling Mount

Photometric Test Report: LL13887

Thermal Test Report: LL1019004T

C0 – C16

Wall Mount

Photometric Test Report: LL13888

Thermal Test Report: LL1019004T

C0 – E1.25 C90 – C1

### Maintained Emergency – 1x26W

Part Code Open Face: NSM126CE

Part Code Grill Face: NSG126CE

**Classifications:**

Ceiling Mount

Photometric Test Report: LL14589

Thermal Test Report: LL1105303T-R01

C0 – C12.5 C90 – C16

Wall Mount

Photometric Test Report: LL14440

Thermal Test Report: LL1105303T-R01

C0 – E1.25 C90 – D1.25

### Stanilite Nexus Monitored Maintained Emergency – 1x26W

Part Code Open Face: NSM126ME-NS

Part Code Grill Face: NSG126ME-NS

**Classifications:**

Ceiling Mount

Photometric Test Report: LL12954

Thermal Test Report: LL0919804T-R02

C0 – D25 C90 – D20

Wall Mount

Photometric Test Report: LL12955

Thermal Test Report: LL0919804T-R02

C0 – D6.3 C90 – D5

### Clevertronics Zone Works Monitored Maintained Emergency – 2x18W

Part Code Open Face: NSM218ME-ZCP

Part Code Grill Face: NSG218ME-ZCP

**Classifications:**

Ceiling Mount

Photometric Test Report: LL13184

Thermal Test Report: LL0919805T-R01

C0 – C25

Wall Mount

Photometric Test Report: LL13183

Thermal Test Report: LL0919805T-R01

C0 – D4 C90 – E2.5

### Tridonic DALI Monitored Maintained Emergency – 2x18W

Part Code Open Face: NSM218DALI-ME

Part Code Grill Face: NSG218DALI-ME

**Classifications:**

Ceiling Mount

Photometric Test Report: LL14783

Thermal Test Report: LL1120001T-R01

C0 – C32

Wall Mount

Photometric Test Report: LL14784

Thermal Test Report: LL1120001T-R01

C0 – E1.6 C90 – E1.6

